

IN REPLY REFER TO: 3809 (U-052)

United States Department of the Interior CE

BUREAU OF LAND MANAGEMENT RICHFIELD DISTRICT OFFICE 150 EAST 900 NORTH RICHFIELD, UTAH 84701



DIVISION OF OIL, GAS & MINING

November 17, 1986

Ms. Pamelyn Jensen Southwestern Portland Cement Company P.O. Box 51 Nephi, Utah 84648

Dear Ms. Jensen:

We are in receipt of your letter of November 3, 1986, regarding certain modifications to Notice UT-056-55N filed under the 43 CFR 3809 regulations. The modifications outlined include a realignment of the existing dirt road where it leaves State Highway 132 and the construction of an additional road along the top of the ridge to the mine site. It is our understanding that the construction of the additional road was a mistake resulting from a miscommunication between Southwestern Portland Cement Company and the contractor.

The total disturbance resulting from upgrading the previously existing road and the construction of the new road totals approximately three and one-half acres. As such, the modification, as outlined in your letter, still falls under the criteria of a Notice as it does not exceed five acres of disturbance. Accordingly, you may proceed with the operation as outlined in your letter. Personnel from our resource area office in Fillmore, Utah, will be in contact with you concerning reclamation of disturbed areas and the placement of a cattleguard at the junction of State Highway 132 and the dirt road leading to your mine site.

Thank you for advising the BLM of the modifications to your exploration plan. Your help in properly managing our public lands is greatly appreciated.

FILE COPY

Sincerely,

Monara J. Hondleton

Donald L. Pendleton District Manager

State of Utah - Division of Oil, Gas & Mining. HRRA